

Florida Department of Environmental Protection



Office of Communications

Ethanol Train Derailment, Port of Tampa

OER Incident# 2013-4i-49336

7/25/13



Firefighting foam, to suppress vapors and prevent ignition







Damaged rail track



Domes where leaks occurred



Uprighting and loading rail cars

